

FIGURE 4.1 Generalized compressibility chart at low P_r . $V_{r1} = V/(RT_c/P_c)$. (Nelson and Obert, 1954)




FIGURE 4.2 Generalized compressibility chart at moderate P_r . $V_{r1} = V/(RT_c/P_c)$. (Nelson and Obert, 1954).